CREATE A NEW JOB





OPEN MENU TOP LEFT OF SCREEN



SELECT THE MAN BOTTOM LEFT



TICK ADMINISTRATOR



SELECT NEW JOB



CLICK IN 'NEW JOB'
TYPE IN YOUR JOBS NAME.
PRESS ENTER
PRESS NEXT

Job Files		
Localisation:		
Geoid Separation:		
Horizontal Shift:		
Linework:	4	
Guideline:		
Survey Topo:		
	Back Next	t 🚫 Cancel

 LOCALISATION: IF YOUR JOB SITE USES THIS UPLOAD IT HERE
GEOID: IF YOUR JOB SITE USES THIS UPLOAD HERE
(YOU CAN FIND THIS INFO OUT FROM YOUR SITES SURVEYOR)
DESIGN LINEWORK—ALL JOBS NEED THIS. IT IS YOUR DESIGN STRINGS, UPLOAD HERE.

Data				
Places	211028_STP_NTH_STG1	design	211028_stp_nth_stg1_tri.dxf	Training linework.dxf
Documents	211028_STP_NTH_STG2	diagnostic	211028_STP_NTH_STG1.dxf	Training surface.dxf
Data	211028_STP_NTH_STG3	File Transfers	211028_stp_nth_stg2_tri.dxf	
Drives	211028_stp_sth_stg1	icons	211028_STP_NTH_STG2.dxf	
Storage HDD (D:)	211028_stp_sth_stg1	Maricopa	211028_STP_NTH_STG3.dxf	
	actual	New Job	211028_stp_sth_stg1_Dump_tri.dxf	
	backups	Put design name here	211028_stp_sth_stg1_Tri.dxf	
	config	questions	211028_stp_sth_stg1.dxf	
	coordshifts	reports	211028_stp_sth_stg2_Tri.dxf	
	aily daily	support	211028_th_stg2.dxf	
	DEMO	TEST	DEMO LINEWORK.dxf	
	DEMO JOB	training	DEMO SURFACE.dxf	
File name: DEMO LINEWORK.dxf			File	type: Site Plan File
				Open Cance

SELECTING LINEWORK: 1. NAVIGATE TO USB DRIVE 2. HIGHLIGHT YOUR DESIGN LINEWORK FILE 3. PRESS OPEN

Job Files		-
Localisation:		
Geoid Separation:		
Horizontal Shift:		
Linework:	DEMO LINEWORK.dxf	
Guideline:		
Survey Topo:		
	Rack Ext	

YOUR LINE WORK HAS BEEN UPLOADED TO THE NEW JOB. PRESS NEXT

Surface Options			-
Surfaces: Remove Add	File Path:		
	Work Type:		
	Fill Style:		
	Fill Colour:	#000000	
	Line Style:		
	Line Colour:	#000000	
	Alert Method:		
		Always on Top	
		Show in Views	
		Back Dext 😣	Cancel

TO ADD SURFACE FILE: PRESS ADD



1. NAVIGATE TO YOUR USB

2. HIGHLIGHT YOUR SURFACE FILE

3. PRESS OPEN

Surface Options			
Surfaces. Remove Add	File Path:	DEMO SURFACE.dxf	
DEMO SURFACE	Work Type:	Design	
	Fill Style:	Solid Fill	
	Fill Colour:	#a52a2a	
	Line Style:	Solid Line	
	Line Colour:	#ITTTT	
	Alert Method:	Not Applicable	
		Always on Top	
		Show in Views	
		eck Next 📀	Cancel

YOUR SURFACE FILE HAS BEEN UPLOADED TO THE JOB. PRESS NEXT

Loo Mapping		
Units of Record:	Metres	•
Transform Method:	Similarity	
Alignment Method:	Align to Grid	
Job Scale:	1.00000000000000	6
60-reference	State Grid Universistandard	
	Back Next 🚫 C	ance

UNITS OF RECORDS: METRES REST DEFAULT SELECT GEO—REF IF YOU ARE USING PUBLISH COORDINATES (CONTACT SITE SURVEYOR TO CONFIRM)

Geo-Reference	
AUSTRALIA	*
AUSTRIA	
> BELGIUM	
BOSNIA	
CANADA	
CHINA	
CROATIA	
CYPRUS	
CZECH	
DENMARK	
> ESTONIA	
FINLAND	
FRANCE	
GERMANY	
GREECE	
HONG KONG	
IPELAND	
ICDAEL	
TALIA	
IADAN	
KODEA	
NUREA	
MODOCCO	
MOROCCO	
NETHERLANDS	
NEW ZEALAND	
NORWAY	
POLAND	
D PORTUGAL	•

IF USING PUBLISHED COORDINATES: SELECT YOUR LOCATION



SELECT YOUR COORD SYSTEM



SELECT YOUR ZONE. PRESS OK

Job Mapping		
Units of Record:	Metres	•
Transform Method:	Similarity	•
Alignment Method:	Align to Grid	
Job Scale:	1.000000000000000	6
Geo-reference	IState Ctrl AUSTRALIA/GDA94/MGA zone 55	
	Bak D Next	ancel

YOUR SELECTION WILL BE DISPLAYED IN THE WINDOW PANE. PRESS NEXT



LAST PAGE—IF YOU DON'T HAVE LOCALISATION IT WILL LOOK LIKE THIS. PRESS FINISH









YOUR NEW JOB IS NOW CREATED AND WILL AUTOMATICALLY BE LOADED. ZOOM OUT TO CHECK LINEWORK IS PRESENT. ENSURE YOU GET CUT/FILL VALUES WHEN ON THE SURFACE.